

## Oil Pump Problem

Escrito por MichaelMorin - 04/04/2018 12:01

---

Hi,

I have a 1997 taurus with the vulcan 3.0l engine. Oil light came on and during troubleshooting engine locked up. Pulled pan and found pos#3 main and pos#3 rod bearings trashed. Was able to save crank but when I checked the oil pump it was ok. pulled drive shaft out of pump and held back in engine (made sure it was locked in drive) when I turn engine the shaft moved only a little bit and then went back to where it started from. I know that in the older engines the distributor turned the oil pump drive shaft but what turns them on the new engines? And is there a common problem of something I should be looking for?

Please help.

I didn't find the right solution from the Internet.

References:-

<https://bit.ly/2q3Rxik>

Business video marketing studio

Thanks

=====